



SFM Fire Inspection Report

Inspection Information

Inspection Date: 05/22/2023

Inspection Type: School-charter - Follow-Up

Inspection No: 016456

Occupancy Class: E

Facility Information

ISD991 Educational Learning Center Montevideo
2419 Washington Avenue Montevideo, MN 56265
Email: kayla.speidel@swwc.org

***Property Use:** ED - Charter elementary

Occupant Loads

No Occupant Loads Found

Primary Contact

Halverson, Mindy (Site Administrator) Work Phone: 320-321-1484 | Email: kayla.speidel@swwc.org

Lindquist, Jacob (State Inspector) Email/Cell: jacob.lindquist@state.mn.us (651) 413-5973

Violations

On the above date, an inspection was conducted for the purposes of fire and life safety. The following conditions were observed that do not meet the minimum requirements of the Minnesota State Fire Code. Failure to correct identified fire and life safety deficiencies in a timely manner is a criminal violation pursuant to Minn. Stat. § 299F.011, subd. 6. There is a variance procedure available. Please contact the inspector named for further assistance.

Code - Description	Violation Status
** MSFC 2020 - 1104.7 : Remove non-approved locking hardware and devices from exit doors. Door handles, pulls, latches, locks and other operating devices on exit doors shall only require a single operation to release the door from the egress side. See MSFC Section 1010.1.9 - Violation Location: - Comments: Remove Unapproved device that inhibits opening the door in the early childcare room ---	Violation Repaired
** MSFC 2020 - 901.4 : Maintain fire protection systems in accordance with the original installation standards. - Violation Location: - Comments: Fire alarm design was provided, notification meets code requirements and copy was saved in occupant file. ---	Violation Repaired

End of Report

Printed: 05/22/2023 08:32